Oil Field Environmental Incident Summary

Responsible Party: HESS CORPORATION
Well Operator: HESS CORPORATION
Well Name: ANTELOPE DEVONIAN UNIT

Field Name: ANTELOPE Well File #:

 Date Incident:
 6/24/2015
 Time Incident:
 07:00
 Facility ID Number:
 402373-01

 County:
 MCKENZIE
 Twp:
 152
 Rng:
 95
 Sec:
 1
 Qtr:
 NW SE

Location Description:

Submitted By: Jason Henry Received By:

Contact Person: Jason Henry

3015 16TH ST SW STE 20

MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.7 MileDistance Nearest Water Well:0.7 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

165 Barrels 155 Barrels 155 barrels

Brine Other

Oil

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/8/2015 Clean Up Concluded: 7/2/2015

Risk Evaluation:

The release occurred above ground and remained inside of the secondary containment berm. A vac truck was dispatched to the location for recovery.

Areal Extent:

N/A - the released remained on location, inside of a secondary containment berm.

Potential Environmental Impacts:

The release occurred above ground and remained inside of the secondary containment berm. A vac truck was dispatched to the location in order to recover as much of the released crude oil as practicable. The impacted soil inside of the secondary containment berm will be excavated and sent

Action Taken or Planned:

A vac truck was dispatched to the location in order to recover as much of the released crude oil as practicable. The impacted soil inside of the secondary containment berm will be excavated and sent off-site for proper disposal.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

Updates

Date: 6/25/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location within the secondary containment. NDIC retains oversight.